

PR-id 90406

ATLAS COPCO XAS66

€ 2.450,-

As-Is, Diesel, Volume flow: $\pm 3,4 - 3,7 \text{ m}^3/\text{min}$,
7bar, Poor Cosmetic Condition, But The
Machine Functions Properly

OP WEBSITE BEKIJKEN



Specifications

Driving mechanism	Wiel aandrijving
??? ???????	1997
????? ???????	1904
??? ???????	YA3-606236-00270916
????? ??????? (???)	880
????? (???)	1.95
????? (???)	1.4
???????? (???)	1.3
???????	Diesel
????? ???? ??????? ???????	Deutz
??? ???????	F3M 1011 F
??? ????????????	3
Min-1 / R.P.M.	2400
?????? ????????????	30
?????? ???????	41

Bar

7

??? ???????

1